

Doncaster Repairs

An extensive range of improvements has been made to the existing Southern MSCP to provide car users with a safe and secure parking experience. The works ensure that the building fits into its new environment in this new quarter of Doncaster.

The concrete parking levels were repaired and treated to safeguard against future corrosion and there was an extensive repainting program.



Before



After

Works undertaken by USL included grinding the rough tamped concrete to improve the finish. Protectosil corrosion inhibitor was then applied to all of the concrete decks. In the running isles the appearance of the concrete was then further enhanced by applying Mastertop 524 to provide a smooth finish. Conideck waterproof wearing surfacing was then applied throughout the car park decks. The appearance of the finished decks is excellent and the difference to the existing decks is dramatic.

The repairs to the soffits and walls was undertaken using Nufins HB mortar, with Nucem mortar applied to the concrete decks. Prior to doing this all the surfaces were power washed as the car park was covered in decades of grime. Once the concrete repairs were completed Nufins covercrete anti carbonation paint was applied providing a bright finish to the car park.



Before



After

See page 2 for more application photographs

FOR MORE INFORMATION PLEASE CONTACT US:

USL STRUCTURECARE

Kingston House
3 Walton Road
Pattinson North
Washington
Tyne & Wear
NE38 8QA
United Kingdom

t: +44(0)191 416 1530
f: +44(0)191 415 4377
w: www.usluk.com
e: info@usluk.com

